

STEAMBOAT SLOUGH Fact Sheet

PL84-99 Sites

Emergency Levee Repairs

Location

River: Steamboat Slough Site Identification #: 20051230-002-004 (River Mile 24.9)

Latitude/Longitude:

38.289305/-121.583273

Nearest Impact Area:

Grand Island
County: Sacramento

Bank: Left

Type of Damage

Bank erosion

Total Length of Repair


205 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Reclamation District 3



For further information, please contact:

Les Schmittner Project Manager U.S. Army Corps of Engineers (916) 440-2263

Lester.C.Schmittner@spk01.usace.army.mil

